

AR-509997

- 1 a. 14 Rags w/ Solvents
- 1 b. 8 ~~Flam/Combustible~~ Paint Sludge
- 1 c. 66 Overpacked Resins etc.
- 1 d. 65 Kylene



## STATE OF ARKANSAS

Department of Pollution Control and Ecology

P. O. Box 8913 Little Rock, Arkansas 72219-8913

Telephone 501-562-7444

1

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Douglas Aircraft Company Attn: R. Tuell M/S C6-59 19503 S. Normandie Avenue, Torrance, CA 90502		4. Generator's Phone (213) 533-7926 or 213-533-7231		5. Transporter 1 Company Name United Pumping Service		6. US EPA ID Number CAI DIOI 7129537711		A. State Manifest Document Number AR- 509997	
7. Transporter 2 Company Name		8. US EPA ID Number		9. Designated Facility Name and Site Address Ensco, Inc. American Oil Road El Dorado, AR 71730		10. US EPA ID Number IAIR DIOI 619714811912		B. State Generator's ID HAH036005698	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers		13. Total Quantity		14. Unit Wt/Vol		I. Waste No.	
a. RQ, Hazardous Waste Solid, N.O.S. (111-Trichloroethane) ORM-E, NA9189 (F001,F005)		012 BLA		13300		P		F001, F005	
b. RQ, Waste, Paint Related Material Flammable Liquid, NA1263 (F002,F003,F005) <del>Combustible Liquid</del>		026 DLM		13000		P		F002, F003, F005 U080, U226, U289 U220, U161	
c. RQ, Waste, Flammable Liquid, N.O.S. (Petroleum Distillates) Flammable Liquid, UN1993 (D001)		011 DLM		03800		P		D001	
d. RQ, Waste, Oxidizer, Corrosive Solid, N.O.S. Oxidizer, NA9194 (D001,D002) (Potassium Nitrate)		035 DJF		04000		P		D001, D002	
J. Additional Descriptions for Materials Listed Above a) WMDS # 146134. Production rags contaminated w/solvents. b) WMDS # 146135. Paint sludge. c) WMDS # 146152. Resins, adhesives, hardeners overpacked. If no alternate TSDF, return to generator 30377#		K. Handling Codes for Wastes Listed Above EMERGENCY RESPONSE INFORMATION: 213-533-7926 Rob Tuell 213-830-1781 Tracy Takahashi							
15. Special Handling Instructions and Additional Information d) WMDS # 146142. Kolene. Load # 65947. In case of accident contact Chemtrec at 800-424-9300. Weights are approximate. DOT Emergency Response Guide #'s a)31 b)26 c)26 d)45.									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and Arkansas state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.									
Printed/Typed Name Robert G. Tuell, Jr.		Signature Robert G. Tuell, Jr.		Month Day Year 07/15/91					
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name SIMPSON		Signature Jim Simpson		Month Day Year 07/15/91					
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year					
19. Discrepancy Indication Space Received 25 BA on line 11B Received 36 DR on line 11D									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name KATHLEEN MOORE		Signature Kathleen Moore		Month Day Year 07/18/91					

EPA Form 8700-22 (Rev. 9-88) Previous edition is obsolete.

NOTICE: THE ORIGINAL AND NOT LESS THAN TWO (2) COPIES MUST MOVE WITH THE HAZARDOUS WASTE SHIPMENT. ONCE DELIVERED, THE TREATMENT/STORAGE/DISPOSAL FACILITY MUST RETURN THIS ORIGINAL COPY TO THE GENERATOR.

BOE-C6-0222784

## GENERAL INFORMATION

The Hazardous Waste manifest is designed to track waste from the point of generation to final disposal (cradle to grave). In order to accomplish this goal, it is essential that all items on the manifest be completed correctly. Incomplete or incorrect manifests are violations of the law, and could make you subject to civil or criminal liabilities as specified in the Federal Regulations and the Arkansas Hazardous Waste Management Code.

### INSTRUCTIONS—IMPORTANT: READ ALL INSTRUCTIONS BEFORE COMPLETING

State and Federal regulations require Generators, Transporters, and Treatment, Storage & Disposal Facilities (TSDFs) to use this form and if necessary the continuation sheet for both inter and intrastate shipments. (Continuation sheets are not provided by the state of Arkansas.)

The Arkansas Manifest contains 6 copies. **ALL COPIES MUST BE LEGIBLE.** This form is designed for use on a 12 pitch (elite) typewriter, a firm ball point pen may also be used only if you press down HARD. The 6 copies must be distributed in the following way:

- ORIGINAL: GENERATOR COPY**—The TSDF will mail back to the generator state where the waste was generated. (WHITE COPY)
- COPY 2: STATE COPY**—The in-state TSDF mails to Arkansas Department of Pollution Control. (YELLOW COPY)
- COPY 3: TSDF COPY**—TSDF keeps this copy for his records. (PINK COPY)
- COPY 4: 2ND TRANSPORTER COPY**—The second transporter keeps for his records. (GOLD COPY)
- COPY 5: 1ST TRANSPORTER COPY**—The first transporter keeps for his records. (GREEN COPY)
- COPY 6: GENERATOR INITIAL COPY**—The generator keeps once first transporter signs off and takes waste. (BLUE COPY)

**IF THE TSDF IS LOCATED OUT-OF-STATE THE IN-STATE GENERATOR MUST SEND A PHOTOCOPY TO THE ARKANSAS DEPARTMENT OF POLLUTION CONTROL ONCE THE MANIFEST HAS BEEN SIGNED OFF BY THE TSDF.**

### MANIFEST FORM ACQUISITION

1. If the destination (consignee) state supplies a manifest and requires its use, then the generator is obligated to obtain the manifest from that state.
2. If the destination state does not supply the manifest, but the generator state does, then the generator is obligated to obtain the manifest form from the generator state.
3. If forms are unavailable from either state the generator may obtain a manifest from any source.

### ARKANSAS WILL NOT ACCEPT THE GENERIC UNIFORM MANIFEST

#### GENERATOR SECTION

- Item 1: **GENERATOR'S US EPA ID NO.—MANIFEST DOCUMENT NO.**—Enter the generator's 12-digit EPA identification number. The manifest document number is a unique 5-digit no. the generator assigns to each manifest.
- Item 2: **PAGE 1 OF**—Enter the total number of pages used to complete this manifest: i.e., the first page plus the number of continuation sheets, if any.
- Item 3: **GENERATOR'S NAME & MAILING ADDRESS**—Enter the name and mailing address of the generator, and provide the site address.
- Item 4: **GENERATOR'S PHONE NUMBER**—Enter a telephone no. with area code where an authorized agent of the generator can be reached in case of an emergency.
- Item 5: **TRANSPORTER 1 COMPANY NAME**—Enter the company name (as notified to EPA) of the first transporter who will transport the waste.
- Item 6: **US EPA ID NUMBER**—Enter the US EPA 12-digit ID number of the first transporter identified in Item 5.
- Item 7: **TRANSPORTER 2 COMPANY NAME**—If applicable, enter the company name (as notified to EPA) of the second transporter who will transport the waste. If more than (2) transporters will be used, use a continuation sheet and list the transporters in the order they will be transporting the waste.
- Item 8: **US EPA ID NUMBER**—If applicable, enter the US EPA 12-digit ID number of the second transporter identified in Item 7.
- Item 9: **DESIGNATED FACILITY NAME & SITE ADDRESS**—Enter the company name and site address of the treatment, storage, disposal facility (TSDF) designated to receive the waste listed on this manifest.
- Item 10: **US EPA ID NUMBER**—Enter the 12-digit US EPA identification number of the designated TSDF listed in Item 9.
- Item 11: **US DOT DESCRIPTION**—All of the following must be entered: the correct US DOT (Dept. of Transportation) name for the waste identified, the assigned DOT Hazard Class and the UN/NA ID Number (e.g.: waste sulfuric acid, corrosive material, UN1832 RQ). The word "waste" must appear as part of the DOT name. If more than 4 wastes are being shipped, 1 must be listed on the continuation sheets must be used (See 49 CFR 172.201).
- Item 12: **CONTAINERS (No. & Type)**—Enter the number of containers for each waste and the appropriate abbreviations from Table 1 (below) for the type of container used.

TABLE 1  
CONTAINER TYPES

DM	Metal drums, barrels, kegs
DW	Wooden drums, barrels, kegs
DP	Fiberboard or plastic drums, barrels, kegs
FP	Tanks portable
TL	Cargo tanks (tank trucks)
TC	Tank cars
DT	Dump truck
CY	Cylinders
CM	Metal boxes, cartons, cases (including roll-offs)
CW	Wooden boxes, cartons, cases
CP	Fiber or plastic boxes, cartons, cases
BA	Burlap, cloth, paper or plastic bags

- Item 13: **TOTAL QUANTITY**—Enter the total quantity of waste described on each line.

### DO NOT USE FRACTIONS

- Item 14: **UNIT (Wt./Vol.)**—Enter the appropriate abbreviation from Table 2 (below) for the unit of measure used in determining the total quantity of waste described on each line.

TABLE 2  
UNITS OF MEASURE

G	-Gallons (liquid only)
P	-Pounds
T	-Tons (2,000 lbs.)
Y	-Cubic yards
L	-Liters (liquids only)
K	-Kilograms
M	-Metric Tons (1,000 kg)
N	-Cubic meters

- Item 15: **SPECIAL HANDLING INSTRUCTIONS & ADDITIONAL INFORMATION**—Use this space to indicate special transportation, treatment, storage, disposal, or Bill of Lading information. If any alternate facility is designated, note it here. For INTERNATIONAL SHIPMENTS, generators must enter the point of departure (city & state) in this space.
- Item 16: **GENERATOR'S CERTIFICATION**—The Generator must read, sign, (by hand), and date the certification. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, air) inserted in the space. If another mode in addition to the highway mode is used, enter the appropriate additional mode in the space.
- Item A: **STATE MANIFEST DOCUMENT NUMBER**—Number preprinted by the state of Arkansas except on the continuation sheets. Enter this number on each continuation sheet attached to the manifest.
- Item B: **STATE GENERATOR ID**—Are numbers issued by state of Arkansas (i.e., PCB, Provisional, or Conditionally Exempt Generator Numbers).
- Item C: **STATE TRAN #1 ID**—Must have Arkansas Permit Number if transporting waste in, through, or out of Arkansas.
- Item D: **TRANSPORTER PHONE**—Enter a telephone number with area code where an authorized agent of the transporter can be reached.
- Item E: **STATE TRAN #2 ID**—If applicable, enter Arkansas Permit Number if carrying waste in, through, or out of the Arkansas.
- Item F: **TRANSPORTER PHONE**—If applicable, enter a telephone number with area code where an authorized agent of the second transporter may be reached.
- Item G: **STATE FACILITY'S ID**—No entry is required by Arkansas.
- Item H: **FACILITY PHONE**—Enter a telephone number with area code of the TSDF designated to receive the waste listed on the manifest.
- Item I: **WASTE NO.**—Enter the 4-digit EPA Hazardous Waste No. as listed in 40 Code of Federal Regulations Part 261.
- Item J: **ADDITIONAL DESCRIPTIONS FOR MATERIALS LISTED BELOW**—List additional description of material and alternate TSDF including TSDF address and EPA ID Number.
- Item K: **EMERGENCY RESPONSE INFORMATION**—Arkansas requires the generator to list an authorized representative name and 24 hour phone number in case of an emergency.

### TRANSPORTER SECTION

- Item 17: **TRANSPORTER 1 ACKNOWLEDGEMENT**—Print or type the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the manifest by signing and entering the date of receipt.
- Item 18: **TRANSPORTER 2 ACKNOWLEDGEMENT**—If applicable, follow instructions for Item 17 for the second transporter.
- Note: **ALL HAZARDOUS WASTE TRANSPORTERS OPERATING IN ARKANSAS MUST HAVE A VALID ARKANSAS TRANSPORTER PERMIT.**

### DESIGNATED FACILITY (TSDF) SECTION

- Item 19: **DISCREPANCY INDICATION SPACE**—The authorized representative of the designated facility must note in this space any significant discrepancy between the waste described on the manifest and the waste actually received at the facility. Any rejected materials should be listed here, along with an explanation of the disposition of the rejected wastes.
- Item 20: **FACILITY OWNER/OPERATOR CERTIFICATION**—Print or type the name of the person accepting the waste on behalf of the owner/operator of the designated TSDF. That person must acknowledge acceptance of the waste described on the manifest by signing and entering the date.

Note: For interstate shipments you may be required to comply with the manifesting requirements of both the receiving and generator states regarding the completion of specific information included in lettered items A-K. Please check with both generator and disposer states for specific requirements.

### BURDEN DISCLOSURE STATEMENT

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W., Washington, D.C., 20460; and to the Office of Information and Regulatory Affairs, Office Of Management and Budget, Washington, D.C., 20503.



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
Generator's Name and Mailing Address		Douglas Aircraft Company Attn: R. Tuell M/S C6-59 19503 S. Normandie Avenue, Torrance, CA 90502		A. State Manifest Document Number <b>AR- 509997</b>		
4. Generator's Phone ( 213 ) 533-7926 or 213-533-7231		6. US EPA ID Number C A D O 8 6 5 1 0 0 0 5 9 1 0 7 4		B. State Generator's ID HAH036005698		
5. Transporter 1 Company Name United Pumping Service		7. Transporter 2 Company Name		C. State Transporter's ID PC 1123 H 602		
6. US EPA ID Number C A D O 7 2 9 5 3 7 7 1		8. US EPA ID Number		D. Transporter's Phone 818-961-9326		
7. Transporter 2 US EPA ID Number		9. Designated Facility Name and Site Address Ensco, Inc. American Oil Road El Dorado, AR 71730		E. State Transporter's ID PC --- H ---		
10. US EPA ID Number A R D O 6 9 7 4 8 1 9 2		11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		F. Transporter's Phone		
a. RQ, Hazardous Waste Solid, N.O.S. (111-Trichloroethane) ORM-E, NA9189 (F001,F005)		12. Containers No. Type		13. Total Quantity		
b. RQ, Waste, Paint Related Material Flammable Liquid, NA1263 (F002,F003,F005)		14. Unit Wt/Vol		I. Waste No.		
c. RQ, Waste, Flammable Liquid, N.O.S. (Petroleum Distillates) Flammable Liquid, UN1993 (D001)		P F001, F005		F002, F003, F005 U080, U226, U289 U220, U161		
d. RQ, Waste, Oxidizer, Corrosive Solid, N.O.S. Oxidizer, NA9194 (D001,D002) (Potassium Nitrate)		D M D001		P D001		
J. Additional Descriptions for Materials Listed Above a) WMDS # 146134. Production rags contaminated w/solvents. b) WMDS # 146135. Paint sludge. c) WMDS # 146152. Resins, adhesives, hardeners overpacked. if no alternate TSDF, return to generator		K. Handling Codes for Wastes Listed Above EMERGENCY RESPONSE INFORMATION: 213-533-7926 Rob Tuell 213-830-1781 Tracy Takahashi				
15. Special Handling Instructions and Additional Information d) WMDS # 146142. Kolene. Load # 65947. In case of accident contact Chemtrec at 800-424-9300. Weights are approximate. DOT Emergency Response Guide #'s a)31 b)26 c)26 d)45.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and Arkansas state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name Robert G. Tuell, Jr.		Signature Robert G. Tuell, Jr.		Month Day Year 07/15/91		
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year		
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name						
Signature						
Month Day Year						

EPA Form 8700-22 (Rev. 9-88) Previous edition is obsolete.

NOTICE: THE ORIGINAL AND NOT LESS THAN TWO (2) COPIES MUST MOVE WITH THE HAZARDOUS WASTE SHIPMENT. ONCE DELIVERED, THE TREATMENT/STORAGE/DISPOSAL FACILITY MUST RETURN THIS ORIGINAL COPY TO THE GENERATOR.



## STATE OF ARKANSAS

Department of Pollution Control and Ecology

P. O. Box 8913 Little Rock, Arkansas 72219-8913

Telephone 501-562-7444

6

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address		6. US EPA ID Number		A. State Manifest Document Number		
Douglas Aircraft Company Attn: R. Tuell M/S C6-59 19503 S. Normandie Avenue, Torrance, CA 90502		d A d d 8 6 5 1 d d d 5 9 1 1 0 7 7		AR- 509997		
4. Generator's Phone ( 213 ) 533-7926 or 213-533-7231		8. US EPA ID Number		B. State Generator's ID		
5. Transporter 1 Company Name		C. State Transporter's ID		C. State Transporter's ID		
United Pumping Service		C A D 0 7 2 9 5 3 7 7 1		PC 1123 H 602		
7. Transporter 2 Company Name		E. State Transporter's ID		D. Transporter's Phone		
		PC - - - - H - - -		818-961-9326		
9. Designated Facility Name and Site Address		10. US EPA ID Number		F. Transporter's Phone		
EnSCO, Inc. American Oil Road El Dorado, AR 71730		A R D 0 6 9 7 4 8 1 9 2		501-863-7173		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers		13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
a. RQ, Hazardous Waste Solid, N.O.S. (111-Trichloroethane) ORM-E, NA9189 (F001,F005)		012 B A		13300	P	F001, F005
b. RQ, Waste, Paint Related Material Flammable Liquid, NA1263 (F002,F003,F005)		026 D M		15 PPPP	P	F002, F003, F005 U080, U226, U239 U220, U161
c. RQ, Waste, Flammable Liquid, N.O.S. (Petroleum Distillates) Flammable Liquid, UN1993 (D001)		011 D M		4038000	P	D001
d. RQ, Waste, Oxidizer, Corrosive Solid, N.O.S. Oxidizer, NA9194 (D001,D002) (Potassium Nitrate)		035 D F		04000	P	D001, D002
16. Special Handling Instructions and Additional Information		17. Handling Codes for Wastes Listed Above		EMERGENCY RESPONSE INFORMATION:		
a) WMS # 146134. Production rags contaminated w/solvents. b) WMS # 146135. Paint sludge. c) WMS # 146152. Resins, adhesives, hardeners overpacked. If no alternate TSDF, return to generator				213-533-7926 Rob Tuell 213-830-1781 Tracy Takahashi		
15. Special Handling Instructions and Additional Information		16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.				
17. Transporter 1 Acknowledgement of Receipt of Materials		18. Transporter 2 Acknowledgement of Receipt of Materials				
Printed/Typed Name		Signature		Month Day Year		
Robert G. Tuell, Jr.		Robert G. Tuell, Jr.		07/15/91		
Printed/Typed Name		Signature		Month Day Year		
Jim Papp		Jim Papp		07/15/91		
19. Discrepancy Indication Space		20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.				
Printed/Typed Name		Signature		Month Day Year		

EPA Form 8700-22 (Rev. 9-88) Previous edition is obsolete.

GENERATOR INITIAL COPY

BOE-C6-0222787



# UNITED PUMPING SERVICE, INC. FIELD WORK ORDER

20866

14016 EAST VALLEY BOULEVARD  
CITY OF INDUSTRY, CALIFORNIA 91746  
PHONE: (818) 961-9326  
FAX (818) 336-7734

PAGE 1 OF 1

CUSTOMER/ADDRESS <i>Mc Donald Douglas</i>	
PHONE NO.	CONTACT <i>II Corp</i>
LOCATION <i>Glendale</i>	

DATE WORK PERFORMED: <i>7-15-91</i>
DATE OF THIS REPORT:
TIME CALL RECEIVED:
CONTRACT NO.:
LOSS REPORT NO./P.O. NO.:

SCOPE OF WORK: <i>Load Dumped Out Range for Disposal</i>
---

EQUIPMENT TYPE	EQUIPMENT NO.	OPERATOR NAME	START TIME	ARRIVE TIME	TIME OUT	STOP TIME	S.T. TIME	O.T. TIME	TOTAL HOURS
<i>XUV #4-</i>	<i>28</i>	<i>John Lyons</i>	<i>0530 A</i>	<i>620 A</i>					

PERSONNEL NAME	TITLE	START TIME	ARRIVE TIME	TIME OUT	STOP TIME	S.T. TIME	O.T. TIME	TOTAL HOURS

DISPOSAL MANIFEST NO.	DISPOSAL SITE	QTY	UNIT
<i>509997</i>	<i>Glendale</i>		<i>2 1/2 yds</i>

CONSUMABLE TYPE	QTY	TYPE	QTY

ADDITIONAL INFORMATION

SIGNED *Ray Takahashi - IT Corp*



# UNITED PUMPING SERVICE, INC. FIELD WORK ORDER

20866

14016 EAST VALLEY BOULEVARD  
CITY OF INDUSTRY, CALIFORNIA 91746  
PHONE: (818) 961-9326  
FAX (818) 336-7734

PAGE 1 OF 1

CUSTOMER/ADDRESS	<i>McDonald Douglas</i>		
PHONE NO.	CONTACT <i>II Corp</i>		
LOCATION	<i>Alhambra</i>		

DATE WORK PERFORMED:	<i>7-15-91</i>
DATE OF THIS REPORT:	
TIME CALL RECEIVED:	
CONTRACT NO.:	
LOSS REPORT NO./P.O. NO.:	

SCOPE OF WORK:	<i>Load Demolition Cart Haze for Disposal</i>
----------------	---

EQUIPMENT: TYPE	EQUIPMENT NO.	OPERATOR NAME	START TIME	ARRIVE TIME	TIME OUT	STOP TIME	S.T. TIME	O.T. TIME	TOTAL HOURS
<i>XUV #4-</i>	<i>28</i>	<i>John Lopez</i>	<i>0530</i>	<i>620</i>					

PERSONNEL NAME	TITLE	START TIME	ARRIVE TIME	TIME OUT	STOP TIME	S.T. TIME	O.T. TIME	TOTAL HOURS

DISPOSAL: MANIFEST NO.	DISPOSAL SITE	QTY	UNIT
<i>509997</i>	<i>Conato</i>		<i>20 p unit</i>

CONSUMABLE: TYPE	QTY	TYPE	QTY

ADDITIONAL INFORMATION:

SIGNED:

*John Lopez - II Corp*